US ERA ARCHIVE DOCUMENT

Unit Name/Designators 5. Unit Lead		Kalamazoo	River/Enbridge Oil Spill	2. Date Prepared 03/07/2012	3. Time Prepared 1700
			er (Name and Position) Leutke, Planning Section Chief		6. Operational Period 0700, 03/01/2012 – 0700, 03/08/2012
•			Personnel Roster Assigne	ed	
Name			ICS Position		Contact Phone
Matthew Haak		Haak	Situation Unit		
			Activity Log		
7ime 0900	Observatio		Major E	vents	
		Observed T Talmadge C near MP1.6 Talmadge C restoration of Confluence Confluence Curtain from Confluence diversion be Confluence	Creek: observed weir str Creek: observed timber in work near MP1.75. Ongoing Temperature eff Drive RDB- overbank sha cobserved water quality cobserved crew removing creek portion of Conflue cobserved backfill and extra cobserved excavation and cobserved removal of the cobserved sampling of the cobserved restoration of cobserved excavation and cobserved excavation and cobserved excavation and cobserved excavation and cobserved during	izing of bypass distructure near MP1.6 mats being remove fects study. een observed. monitoring. It is garage boom and ence. Excavation work arcording the first diversion e diversion structure diversion structure e diversion and removal of the diversion structure.	charge de and sediment bund first rsion box. re. box. re culvert that re. to restoration. diversion moval of the tructure.
1500	Return to I	CP			

Matthew Haak, Situation Unit Leader, USEPA-START